Luoyang Zhongsen Refractory Co., Limited

Yaowan Village, South Dukang Road, Yichuan County, Luoyang City, Henan Province, P.R.CHINA TEL: 0086-379-69351288 WEB: www.zhongsen-refractory.com

PRODUCT DATA SHEET & MATERIAL SAFETY DATA SHEET

Identification of the Chemical and the Origin

Product

Country of Origin

方。中森 ngsen refractor

: China

Manufacturer of Material

Picture of Product:

: Luoyang Zhongsen Refractory Co., Limited

: Fused Calcium Aluminate for Steel Making Industry



Physical Specifications & Package

Color	: Brown/Silver
A12O3	: 35%-48%
CaO	: 45%-65%
SiO2	: <6%
MgO	: 1%-6%
Sizes	: Subject to request
Package	: 1 Ton Big Bag, 25kg Bag and 40 Bags on a Pallet

Health Hazard Information

Health Effects	
Swallowed	: May cause harm to body, seek medical help.
Eye	: Irritation may result if recommended exposure limits are
	Exceeded
Skin	: No harm to skin.



Luoyang Zhongsen Refractory Co.,Limited Yaowan Village, South Dukang Road, Yichuan County, Luoyang City, Henan Province,P.R.CHINA

TEL: 0086-379-69351288 WEB: www.zhongsen-refractory.com

Inhaled	: Dust in excess of recommended exposure limits may result In irritation of the respiratory tract.
First Aid	
Swallowed	: May cause harm to body, seek medical help.
Eye	: Rinse with water, seek medical help if necessary.
Skin	: No harm to skin.

Inhaled : Remove to fresh air

Advice to Doctor

Chronic lung conditions may be aggravated by exposure to high concentration of dust.

Precautions for use

Exposure Limits	: Nuisance Dust
Ventilation	: Local exhaust recommended in case of dusting
Personal Protection	: Approved eye goggles & dust mask to be worn in dusty
	Conditions
Flammable	: Non-flammable

Safe Handling Information

Storage and Transport	: Care should be taken to avoid dusting
Spills and Disposal	: Spillage may result in slippery conditions
Fire / Explosion Hazard	: None
Other Information	: (Material to avoid) – Hydrofluoric Acid
	Use standard good manufacturing practices when handling
	Material.